

3.7 nominal

2.01

0.000

0.000

2.24

Optical Axis

7.43

0.000

S100 Stand with Model 50 Mounting

Dimensions in Inches, Tolerances: 0.XX = +/- 0.015
0.XXX = +/- 0.005

Scale: Full	Sheet: 1 of 1	CAGE 50223	Rev: D
-------------	---------------	------------	--------

