



S100 Stand with T100 Mounting

Dimensions in Inches, Tolerances: 0.XX = +/- 0.015
 0.XXX = +/- 0.005

Scale: Full	Sheet: 1 of 1	CAGE 50223	Rev: D
-------------	---------------	------------	--------

